GOVERNMENT OF ANDHRA PRADESH ABSTRACT

Secretariat Buildings – General Administration Department – Estimate for Replacement of Existing Smoke Detectors in "D" block in the premises of A.P. Secretariat, Hyderabad – Administrative Sanction – Orders – Issued.

GENERAL ADMINISTRATION (SB.I) DEPARTMENT

<u>G.O.Rt.No. 3606</u> <u>Dated: 04.08.2012</u> Read:-

From the Electrical Engineer (Genl), R&B, Hyderabad, Lr.No.EE/G1/HD/DB/TA2/2012-13/1382, dated 04.07.2012

ORDER:

In the circumstances reported by the Electrical Engineer (Genl), R&B, AC Guards, Hyderabad in the reference read above and after examination of the matter, Government hereby accorded administrative sanction for an amount of Rs.14,00,000.00 (Rupees Fourteen lakhs only) towards Replacement of Existing Smoke Detectors in "D" block in the premises of A.P. Secretariat, Hyderabad on the responsibility of Electrical Engineer (GL) (R&B) Hyderabad subject to following due procedure and also subject to production of the work done certificate at the time of issue of L.O.C.

- 2. The expenditure shall be debited to the head of account "2059 Public works 01 Office buildings MH 053 Maintenance and repairs SH (10) Buildings of General Administration Department 270 Minor works 272 Maintenance"
- 3. This order does not require the concurrence of Finance Department as per rules in force.

(BY ORDER AND IN THE NAME OF THE GOVERNOR OF ANDHRA PRADESH)

AJYA MISRA
PRINCIPAL SECRETARY TO GOVERNMENT (POLL)

To

The Chief Engineer (R&B) Buildings, Hyderabad. The Electrical Engineer (General), R&B, AC Guards, Hyderabad. The Dy. Executive Engineer (Electrical), Sectt. Sub-division, Hyderabad. SF/SC.

//FORWARDED:: BY ORDER//

SECTION OFFICER